

## State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R STYLER Executive Director JOHN R BAZA
Division Director

## Inspection Report Minerals Regulatory Program

Date: October 21, 2008

| Reviewed: | TR |
|-----------|----|
|           |    |

| ; 10/16/2008                      |  |  |
|-----------------------------------|--|--|
| Inspection Date: 10/16/2008       |  |  |
| Time: 9:00 am Mine Status: Active |  |  |
|                                   |  |  |

|      | Elements of Inspection  | Evaluated   | Comment     | Enforcement |
|------|---|-------------|-------------|-------------|
| 1,   | Permits, Revisions, Transfer, Bonds   | $\boxtimes$ | $\boxtimes$ |             |
| 2    | Public Safety (shafts, adits, trash, signs, highwalls)                      |             |             |             |
| 3.   | Protection of Drainages / Erosion Control                                   |             |             |             |
| 4.   | Deleterious Material  |             |             |             |
| 5,   | Roads (maintenance, surfacing, dust control, safety)                        |             |             |             |
| 6.   | Concurrent Reclamation  |             |             |             |
| 7    | Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) |             | $\boxtimes$ |             |
| 8    | Water Impoundments  |             |             |             |
| 9    | Soils   |             |             |             |
| 10.  | Revegetation  | $\boxtimes$ |             |             |
| -11. | Air Quality   |             |             |             |
| 12.  | Other   |             |             |             |

Bond Amount: \$8,000 Permit fee: Delinquent

Purpose of Inspection: This was a routine annual inspection of the site.

Inspection Summary: Photos attached.

- 1) The permit fee for 2008 has not been paid.
- 7) The pit in the pictures will eventually need to be filled in
- 9) No topsoil was stockpiled

Conclusions and Recommendations: The site had good regenerative growth with native plants in the area. Any revegetation should not be difficult to achieve. Concurrent reclamation is recommended for any disturbances that can be reclaimed (i.e. contouring, seeding, etc.). Operator needs to pay annual fees. Operator needs to stockpile topsoil for reclamation. DOGM will continue to monitor this site.

Inspector's Signature

BG:vs

cc Todd Anderson

O:\M035-SaltL == \$350032-DJN\inspections\insp-10162008 doc



Looking down on disturbance



Road coming from Camp-Williams property to site



Boulders being mined for landscaping



Disturbed area





Recent activity tracks



Pit that will need to be filled.



Mining area looking west from the east

More disturbances.